



December 13, 2001

Grace Lin
Intertek Testing Services
ETL SEMKO
1950 Evergreen Blvd., Suite 100
Duluth, GA 30096

Phone: 678-775-2400

Dear Ms Lin:

Identified below are the differences between the Lifeline Systems Model SL318/CL320 and the SL/CL324:

- 1) a new microprocessor is used.
- 2) power is applied to the microprocessor through a new trace.
- 3) the microprocessor clock is changed to a different circuit.
- 4) control connections to the microprocessor are modified.
- 5) two component values in the RF circuit, not affecting output power or frequency, are changed.

Please feel free to use this information for FCC submittal.

Sincerely,

SIGNED

Clyde Dottin
Manager, Engineering Services
Lifeline Systems

Lifeline Systems
111 Lawrence Street
Framingham, MA
01702-8156
Phone: 508-988-1000
Fax: 508-988-1384
www.lifelinesys.com