


APPENDIX B-Page 1 of 4 Tel: +886 2 26099301 Fax: +886 2 26099303

B.1 Conducted Emission Measurement



FRONT VIEW



BACK VIEW


File Number: C1M2010180For Report Number: EM-F200486, EM-F200487, EM-F200488, EM-F200490This test report may be reproduced in full only. The document may only be updated by Audix TechnologyCorp. personnel. Any changes will be noted in the Document History section of the report.



APPENDIX B-Page 2 of 4 Tel: +886 2 26099301 Fax: +886 2 26099303

B.2 Radiated Measurement at Chamber

Frequency Below to 1GHz



Frequency Above to 1GHz



File Number: C1M2010180For Report Number: EM-F200486, EM-F200487, EM-F200488, EM-F200490This test report may be reproduced in full only. The document may only be updated by Audix TechnologyCorp. personnel. Any changes will be noted in the Document History section of the report.



AUDIX Technology Corp. No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan APPENDIX B-Page 3 of 4 Tel: +886 2 26099301 Fax: +886 2 26099303

Partner System



 File Number: C1M2010180
 For Report Number: EM-F200486, EM-F200487, EM-F200488, EM-F200490



APPENDIX B-Page 4 of 4 Tel: +886 2 26099301 Fax: +886 2 26099303

B.3 RF Conducted Measurement



 File Number: C1M2010180
 For Report Number: EM-F200486, EM-F200487, EM-F200488, EM-F200490