


Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303





| | | | |
|--|--------------|--------------|--------------------------------|
| Test Date | 2019/09/19 | Temp./Hum. | 25°C/54% |
| Cable Loss | 0.50dB | Test Voltage | AC 120V, 60Hz (via AC Adapter) |
| Mode | 802.11n-HT40 | Tested By | Martin Chen |
| Frequency | TX 2422MHz | | |
| Simultaneous Factor10 log(n) (Note: "n" is antenna number) | | | 3 |



Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


| | | | |
|--|--------------|--------------|--------------------------------|
| Test Date | 2019/09/19 | Temp./Hum. | 25°C/54% |
| Cable Loss | 0.50dB | Test Voltage | AC 120V, 60Hz (via AC Adapter) |
| Mode | 802.11n-HT40 | Tested By | Martin Chen |
| Frequency | TX 2442MHz | | |
| Simultaneous Factor10 log(n) (Note: "n" is antenna number) | | | 3 |




Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303


| | | | |
|--|--------------|--------------|--------------------------------|
| Test Date | 2019/09/19 | Temp./Hum. | 25°C/54% |
| Cable Loss | 0.50dB | Test Voltage | AC 120V, 60Hz (via AC Adapter) |
| Mode | 802.11n-HT40 | Tested By | Martin Chen |
| Frequency | TX 2452MHz | | |
| Simultaneous Factor10 log(n) (Note: "n" is antenna number) | | | 3 |



| | | | |
|--|--------------|--------------|--------------------------------|
| Test Date | 2019/09/19 | Temp./Hum. | 25°C/54% |
| Cable Loss | 0.50dB | Test Voltage | AC 120V, 60Hz (via AC Adapter) |
| Mode | 802.11n-HT40 | Tested By | Martin Chen |
| Frequency | TX 2462MHz | | |
| Simultaneous Factor10 log(n) (Note: "n" is antenna number) | | | 3 |







| | | | |
|--|---------------|--------------|--------------------------------|
| Test Date | 2019/09/19 | Temp./Hum. | 25°C/54% |
| Cable Loss | 0.50dB | Test Voltage | AC 120V, 60Hz (via AC Adapter) |
| Mode | 802.11ax-HE20 | Tested By | Martin Chen |
| Frequency | TX 2412MHz | | |
| Simultaneous Factor10 log(n) (Note: "n" is antenna number) | | | 3 |



Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303






| | | | |
|--|---------------|--------------|--------------------------------|
| Test Date | 2019/09/19 | Temp./Hum. | 25°C/54% |
| Cable Loss | 0.50dB | Test Voltage | AC 120V, 60Hz (via AC Adapter) |
| Mode | 802.11ax-HE20 | Tested By | Martin Chen |
| Frequency | TX 2442MHz | | |
| Simultaneous Factor10 log(n) (Note: "n" is antenna number) | | | 3 |




Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303






| | | | |
|--|---------------|--------------|--------------------------------|
| Test Date | 2019/09/19 | Temp./Hum. | 25°C/54% |
| Cable Loss | 0.50dB | Test Voltage | AC 120V, 60Hz (via AC Adapter) |
| Mode | 802.11ax-HE20 | Tested By | Martin Chen |
| Frequency | TX 2462MHz | | |
| Simultaneous Factor10 log(n) (Note: "n" is antenna number) | | | 3 |



| | | | |
|--|---------------|--------------|--------------------------------|
| Test Date | 2019/09/19 | Temp./Hum. | 25°C/54% |
| Cable Loss | 0.50dB | Test Voltage | AC 120V, 60Hz (via AC Adapter) |
| Mode | 802.11ax-HE20 | Tested By | Martin Chen |
| Frequency | TX 2472MHz | | |
| Simultaneous Factor10 log(n) (Note: "n" is antenna number) | | | 3 |







| | | | |
|--|---------------|--------------|--------------------------------|
| Test Date | 2019/09/19 | Temp./Hum. | 25°C/54% |
| Cable Loss | 0.50dB | Test Voltage | AC 120V, 60Hz (via AC Adapter) |
| Mode | 802.11ax-HE40 | Tested By | Martin Chen |
| Frequency | TX 2422MHz | | |
| Simultaneous Factor10 log(n) (Note: "n" is antenna number) | | | 3 |




Audix Technology Corp.
 No. 53-11, Dingfu, Linkou, Dist.,
 New Taipei City 244, Taiwan

Tel: +886 2 26099301
Fax: +886 2 26099303

| | | | |
|--|---------------|--------------|--------------------------------|
| Test Date | 2019/09/19 | Temp./Hum. | 25°C/54% |
| Cable Loss | 0.50dB | Test Voltage | AC 120V, 60Hz (via AC Adapter) |
| Mode | 802.11ax-HE40 | Tested By | Martin Chen |
| Frequency | TX 2442MHz | | |
| Simultaneous Factor10 log(n) (Note: "n" is antenna number) | | | 3 |








| | | | |
|--|---------------|--------------|--------------------------------|
| Test Date | 2019/09/19 | Temp./Hum. | 25°C/54% |
| Cable Loss | 0.50dB | Test Voltage | AC 120V, 60Hz (via AC Adapter) |
| Mode | 802.11ax-HE40 | Tested By | Martin Chen |
| Frequency | TX 2452MHz | | |
| Simultaneous Factor10 log(n) (Note: "n" is antenna number) | | | 3 |







| | | | |
|--|---------------|--------------|--------------------------------|
| Test Date | 2019/09/19 | Temp./Hum. | 25°C/54% |
| Cable Loss | 0.50dB | Test Voltage | AC 120V, 60Hz (via AC Adapter) |
| Mode | 802.11ax-HE40 | Tested By | Martin Chen |
| Frequency | TX 2462MHz | | |
| Simultaneous Factor10 log(n) (Note: "n" is antenna number) | | | 3 |



| | | | |
|--|------------|--------------|--------------------------------|
| Test Date | 2019/09/19 | Temp./Hum. | 25°C/54% |
| Cable Loss | 0.50dB | Test Voltage | AC 120V, 60Hz (via AC Adapter) |
| Mode | BLE | Tested By | Martin Chen |
| Frequency | TX 2402MHz | | |
| Simultaneous Factor10 log(n) (Note: "n" is antenna number) | | | 0 |



| | | | |
|--|------------|--------------|--------------------------------|
| Test Date | 2019/09/19 | Temp./Hum. | 25°C/54% |
| Cable Loss | 0.50dB | Test Voltage | AC 120V, 60Hz (via AC Adapter) |
| Mode | BLE | Tested By | Martin Chen |
| Frequency | TX 2440MHz | | |
| Simultaneous Factor10 log(n) (Note: "n" is antenna number) | | | 0 |



| | | | |
|--|------------|--------------|--------------------------------|
| Test Date | 2019/09/19 | Temp./Hum. | 25°C/54% |
| Cable Loss | 0.50dB | Test Voltage | AC 120V, 60Hz (via AC Adapter) |
| Mode | BLE | Tested By | Martin Chen |
| Frequency | TX 2480MHz | | |
| Simultaneous Factor10 log(n) (Note: "n" is antenna number) | | | 0 |

