


APPENDIX G

: LABEL INFORMATION





A CAUTION

A PRECAUCIÓN

Service personnel: When disassembling upper parts of cooktop from base for service, tilt upper parts up slightly and disconnect wire harnesses before continuing disassembly.


X To be disassembled by authorized service personnel only.

Personal de servicio: Al desmontar de la base las partes superiores de la placa de cocción para su reparación, incline las partes superiores hacia arriba levemente y desconecte los arneses de cables antes de continuar con el desmontaje.

El desmontaje solo deberá ser realizado por personal de servicio autorizado.











CBIH3613BE

LG Electronics Inc. http://www.lg.com

1-800-243-0000 (USA) 1-888-542-2623 (CANADA)

(USA Only / Seulement pour USA)
This device complies with part 15 of the FCC Rules.
Operation is subject to the following two conditions:
(1) This device may not cause harmful interference, and

(1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation

0 48231 34759 2

S/N: 405KMMM00001 Imp. by/por 111 Sylvan Ave. Englewood Cliffs, NJ 07632 (USA) Imp. by/par LG Electronics Canada Inc. North York, ON M9L 2X6 (Canada) Made in Korea
Fabriqu_82 en Cor_82
Hecho en Corea

< Box label >