

Issue Date: 11 August, 2010 Report No.: RY1008Z11R1 Model: GN-1060

## Test setup photographs 3

## Module installed into a host 3.1





**RF Technologies Ltd.**472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan
Telephone: +81+(0)45- 534-0645, FAX: +81+(0)45- 534-0646, Web: http://www.rft.jp





### **Antenna Port Measurements** 3.2




**RF Technologies Ltd.**472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan
Telephone: +81+(0)45-534-0645, FAX: +81+(0)45-534-0646, Web: http://www.rft.jp



Issue Date: 11 August, 2010 Report No.: RY1008Z11R1 Model: GN-1060

#### **Radiated spurious emissions** 3.3







Issue Date: 11 August, 2010 Report No.: RY1008Z11R1 Model: GN-1060

# AC power line conducted emissions



**RF Technologies Ltd.**472, Nippa-cho, Kohoku-ku, Yokohama, 223-0057, Japan
Telephone: +81+(0)45-534-0645, FAX: +81+(0)45-534-0646, Web: http://www.rft.jp