

April 28,2000

**Federal Communications Commission
Equipment Authorization Division,
Applications Processing Branch
7435 Oakland Mills Road
Columbia, MD 21046**

RE) FCC ID: BRWEXPERT4 (EA97448)

To whom it may concern;

Please refer to the additional information listed below while reviewing the BRWEXPERT4 System.

1) Section 95.645 (b) states that plug-in crystals must not be accessible to the user. Indicate whether or not crystals are accessible to the user.

Although the transmitter crystal is visible from the back of the transmitter, each crystal is glued in place prior to shipment making it a permanent installation. Consumer removal of the crystal will normally result in damage to the crystal. Therefore, frequency changes are done at the service center only.

2) The Manual must contain warnings per section 95.653

A) Please refer to the manual attachment for this information

B) All content for operation is contained in the instruction manual.

1) All instructions are contained in the instruction manual.

2) There are no adjustments accessible to the user that would be in violation with the FCC rules, except as noted in the section #3 below.

3) Noted. We will be adding the following information to the instruction manual under "Frequency Chart":

"Note: The Federal Communications Commission (FCC) requires that changes in radio frequency must be performed by an authorized service technician only (Horizon Service Center).

Any frequency changes made by a non-certified technician may result in a violation of the FCC rules"

4) This section is not applicable to our use.

If there is any further information required, please contact me directly at:

Horizon Hobby Distributors
ATTN: Len Sabato
Fax: 217-355-0058
Phone: 217-352-1958 Ext. 454
lsabato@horizonhobby.com

Best Regards;
Len Sabato