



TTI-P-G 158



---

## **Appendix for the Report**

# **Dosimetric Assessment of the Bang & Olufsen BeoCom 1 (FCC ID: BV5BEOCOM1) According to the FCC Requirements**

## **Responds to FCC request**

September 03, 2003

**IMST GmbH**

**Carl-Friedrich-Gauß-Str. 2**

**D-47475 Kamp-Lintfort**

Customer

**Bang & Olufsen Telecom**

**Kjeldsmarkvej 1**

**DK-7600 Struer Denmark**

The test results only relate to the items tested.  
This report shall not be reproduced except in full without the written  
approval of the testing laboratory.

1. The vertical centerline drawn does not agree with the definition of the "cheek" position Clause 6.4.1 paragraph (b) of the IEEE P1528/D1.2, April 21, 2003. Please follow the instructions and definitions under that section. And acoustic output should also be identified and pointed in the drawing. Please provide a new drawing for question.



Fig. 1: Used reference lines.

Indeed there was a failure in the first drawing, please find now the rotated lines.