



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

August 23, 2004

RE: DBTEL, Inc

FCC ID: BW3-DB-6645-01

I have one specific comment on this Application. Depending on your responses, kindly understand there may be additional comments.

- 1.) Your "Change Letter" simply states that more capacitors and resistors were added to the main board. Could you kindly be more specific as to why the new components were added? Was there a specific problem they were trying to solve? Or was the manufacturer trying to improve performance?

William H. Graff  
President and Director of Engineering

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.