Report No. 0275-08 (FCC ID: BYM900 BP)

ATTESTATION STATEMENT:

All tests according to FCC Part 15, Paragraphs 15.107(a), 15.109(a), 15.209, and 15.249 were

- Performed
- ☐ Not Performed

The Equipment Under Test

- - Fulfills the FCC Part 15, Paragraphs 15.107(a), 15.109(a), 15.209, and 15.249 requirements.
- □ **Does not** fulfill the general approval requirements cited on page 1.

- TÜV PRODUCT SERVICE, INC. -

Mary Whohington

Responsible Engineer:

Responsible Technician:

Dail U fyr

Mary Washington (EMC Engineer)

David Gray

(EMC Senior Technician)