



228 Ambassador Drive
Mississauga ON
Canada
L5T 2J2

July 5, 2010

Office of Engineering and Technology

Re: FCC ID BZ5DTT250M

Reference code # 13EA186523

Dear Sir or Madame:

I just recently submitted a Type Certification Application in which I realized after the fact that I made a mistake on the frequency tolerance specification. The specification (all three) should read 0.002% for frequency Tolerance and not 0.02%. As per the test report, we do indeed meet the tighter specification – it was simply a mistake on the data input that I made. Please change the application to reflect this.

Sincerely,

A handwritten signature in black ink, appearing to read "John Tremblay". The signature is fluid and cursive, with a prominent loop at the end.

John Tremblay
V. P. Engineering



LARCAN

U.S. Tel: 1-303-665-8000 Fax: 1-303-673-9900 **Canada** Tel: 1-905-564-9222 Fax: 1-905-564-9244
www.larcan.com Email: sales@larcan.com