



228 Ambassador Drive
Mississauga ON
Canada
L5T 2J2

November 8, 2010

Bette Taube
Office of Engineering and Technology

Re: FCC ID BZ5MXI501U
Correspondence Reference number 39272

Ms. Taube:

With regards to the discrepancies on the FCC Label/Location Info exhibit, I apologize for the typographical error on the sheet. The header should indeed read BZ5MXI501U and not BZ5MXI501UD. You will likely notice that this typo appears on the header of every exhibit. I have included the FCC Label/location exhibit, corrected to read properly.

Sincerely,

A handwritten signature in black ink, appearing to read "John Tremblay". The signature is fluid and cursive, with the first and last names being more prominent.

John Tremblay
V. P. Engineering



LARCAN

U.S. Tel: 1-303-665-8000 Fax: 1-303-673-9900 **Canada** Tel: 1-905-564-9222 Fax: 1-905-564-9244
www.larcan.com Email: sales@larcan.com

BZ5MXI501U
Application for FCC Certification
500 Watt Digital Television Translator

FCC Label/Label & Location:

