



228 Ambassador Drive
Mississauga ON
Canada
L5T 2J2

November 20, 2009

Stanley Lyles
FCC Application Processing Branch
Office of Engineering and Technology

Re: FCC ID BZ5MXI802UD (currently requested to change to BZ5MXI802U);
Correspondence Reference Number: 38365

Dear Sir:

With regards to the discrepancy between the requested equipment rating and the actual measured power reported in the test report, We have repeated the power measurement with power output calibrated to 325W. The channel of the unit had been changed from the original channel 51 (the bandpass filter had been retuned to channel 39) since the original tests were done in June. Regardless, this power is representative of the product across all the operating channels noted previously.

I hope that this addresses the items of concern with this submission and will allow further processing of this application. Should you have any further concerns, please do not hesitate to contact me.

Sincerely,



LARCAN

U.S. Tel: 1-303-665-8000 Fax: 1-303-673-9900 **Canada** Tel: 1-905-564-9222 Fax: 1-905-564-9244
www.larcan.com **Email: sales@larcan.com**



A handwritten signature in black ink, which appears to read "John Tremblay". The signature is fluid and cursive.

John Tremblay
V. P. Engineering

A decorative horizontal line with a gradient of colors (purple, blue, green, yellow, orange) that ends in a stylized orange wave graphic.

LARCAN

U.S. Tel: 1-303-665-8000 Fax: 1-303-673-9900 **Canada** Tel: 1-905-564-9222 Fax: 1-905-564-9244
www.larcan.com Email: **sales@larcan.com**