

Response to E05-000158-1

1. A new general agreement has been uploaded.
2. RSS-212 is correct.
3. A revised test report has been uploaded.
4. The test method has been changed in the test report.
5. Please change the 731 form to show an equipment class of DXX.
6. The test report now includes bandedge plots.
7. A photo of the wiring side of the board has been uploaded.