

Refer No. : 61116302-RP1 Report No.: 70226306-RP1 Page <u>31</u> of <u>47</u>

APPENDIX SETUP PHOTOS

RADIATED EMISSION MEASUREMENT SETUP







Refer No. : 61116302-RP1 Report No. : 70226306-RP1 Page 32 of 47





Refer No. : 61116302-RP1 Report No. : 70226306-RP1 Page 33 of 47

USB Wireless Mode







Refer No. : 61116302-RP1 Report No. : 70226306-RP1 Page 34 of 47





Refer No. : 61116302-RP1 Report No.: 70226306-RP1 Page <u>35</u> of <u>47</u>







Refer No. : 61116302-RP1 Report No. : 70226306-RP1 Page 36 of 47





Refer No. : 61116302-RP1 Report No.: 70226306-RP1 Page <u>37</u> of <u>47</u>

AC / DC Wireless Mode








Refer No. : 61116302-RP1 Report No. : 70226306-RP1 Page 38 of 47





Refer No. : 61116302-RP1 Report No.: 70226306-RP1 Page <u>39</u> of <u>47</u>







Refer No. : 61116302-RP1 Report No. : 70226306-RP1 Page 40 of 47





Refer No. : 61116302-RP1 Report No.: 70226306-RP1 Page <u>41</u> of <u>47</u>

AC/DC Wirless w/o Dock Mode







Refer No. : 61116302-RP1 Report No. : 70226306-RP1 Page 42 of 47





Refer No. : 61116302-RP1 Report No. : 70226306-RP1 Page 43 of 47

RADIATED RF MEASUREMENT SETUP








Refer No. : 61116302-RP1 Report No. : 70226306-RP1 Page 44 of 47






Refer No. : 61116302-RP1 Report No. : 70226306-RP1 Page 45 of 47

RF PORT COUNTED MEASURE SETUP







Refer No. : 61116302-RP1 Report No.: 70226306-RP1 Page <u>46</u> of <u>47</u>

POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP

AC / DC Charging Mode







Refer No. : 61116302-RP1 Report No.: 70226306-RP1 Page <u>47</u> of <u>47</u>

