

To :	Compliance Certificate Service	From :	I. Y. Lee
Attn :	Mr. Mike Kuo	Ref. No.	05-IST(Y)-0144
CC:	Mr. Scott Wang	Date :	March 29, 2005
Tel No.	+ 1 408 463 0885	Fax No.	+ 1 408 463 0888
Subject : Permissive II change application of C5F7NF0015			
<input checked="" type="checkbox"/> Urgent <input type="checkbox"/> Confirm <input checked="" type="checkbox"/> Request			

Dear Mr. Mike Kuo

We would like to apply the permissive II change of C5F7NF0015.

The change is as follows ;

➤ Power board changing

Model Name	Model description	TCB Issued Date	Applied Loader	Applied Tuner
RV4000 SV294 DF-S04 VR2940 VR2945	Basic Model	06/07/2004	BTC	LG, Alps
RV4000 SV294 DF-S04 VR2940 VR2945	Permissive II Change (Loader change)	09/02/2004	LITE-ON	LG, Alps
DVR-S04 DF-L71N	Permissive II Change (Front PCB change)	09/02/2004	BTC	Alps
DVR-S04 DF-L71N	Permissive II Change (Front change)	10/20/2004	LITE-ON	Alps
RV4000 SV294 DF-S04 VR2940 VR2945	Permissive II Change (Fan add)	11/17/2004	LITE-ON BTC	LG, Alps
DVR-S04 DF-L71N	Permissive II Change (Fan add)	11/17/2004	LITE-ON BTC	LG, Alps
DF-N71N	Permissive II Change (Power board change)		LITE-ON	Alps

The others, schematic, part list, user manual and operational descriptions are same with the origin.

Please find information in your web application system.

I hope your kindness.



I.Y.Lee / EMC Engineer

iylee@ist.re.kr