

To :	Compliance Certificate Service	From :	I. Y. Lee
Attn :	Mr. Mike Kuo	Ref. No.	05-IST(Y)-0185
CC:	Mr. Scott Wang	Date :	May 12, 2005
Tel No.	+ 1 408 463 0885	Fax No.	+ 1 408 463 0888
Subject : Permissive II change application of C5F7NF0015			
<input checked="" type="checkbox"/> Urgent <input type="checkbox"/> Confirm <input checked="" type="checkbox"/> Request			

Dear Mr. Mike Kuo

We would like to apply the permissive II change of C5F7NF0015.

The change is as follows ;

➤ Front panel Change

Model Name	Model description	TCB Issued Date	Applied Loader	Applied Tuner
RV4000 SV294 DF-S04 VR2940 VR2945	Basic Model	06/07/2004	BTC	LG, Alps
RV4000 SV294 DF-S04 VR2940 VR2945	Permissive II Change (Loader change)	09/02/2004	LITE-ON (DDW-451S)	LG, Alps
RV4000 SV294 DF-S04 VR2940 VR2945	Permissive II Change (Adding new loader)	04/14/2005	LITE-ON (DDW-813S)	LG, Alps
VR2946	Permissive II Change (Front panel change)		LITE-ON (DDW-813S)	LG, Alps

The others, schematic, part list, user manual and operational descriptions are same with the origin.

Please find information in your web application system.

I hope your kindness.



I.Y.Lee / EMC Engineer

iylee@ist.re.kr