

OCT 22 1998

5. Identification Label

▶ FCC ID : C5F7NF86MO9000 ◀

IDENTIFICATION LABEL

<p>DAEWOO MICROWAVE OVEN (HOUSEHOLD) MODEL NO.: KOR-861G SERIAL NO.: MANUFACTURED: POWER INPUT 50HZ 120V AC ONLY 1.35KW SINGLE PHASE WITH GROUNDING.</p> <div style="display: flex; align-items: center; margin-top: 5px;"> <div style="border: 1px solid black; padding: 2px; margin-right: 5px;"> FCC ID: C5F7NF86MO9000 MADE IN KOREA </div> </div> <p>DHHS CODE: H7NF DISTRIBUTED BY: DAEWOO ELECTRONICS CORPORATION OF AMERICA, 120 CHUBB AVENUE LYNDHURST, NEW JERSEY 07037, U.S.A</p>	<p>CAUTION *THIS DEVICE IS TO BE SERVICED ONLY BY PROPERLY QUALIFIED SERVICE PERSONNEL. CONSULT THE SERVICE MANUAL FOR PROPER SERVICE PROCEDURES TO ASSURE CONTINUED COMPLIANCE WITH THE FEDERAL PERFORMANCE STANDARD FOR MICROWAVE OVENS AND FOR PRECAUTIONS TO BE TAKEN TO AVOID POSSIBLE EXPOSURE TO EXCESSIVE MICROWAVE ENERGY.</p> <p>WARNING *DISCONNECT APPLIANCE BEFORE SERVICING. REMOVAL OF ENCLOSURE WITH PRODUCT ENERGIZED MAY EXPOSE SERVICEMAN TO HAZARDOUS HIGH-VOLTAGE POTENTIALS. *TO ENSURE CONTINUED PROTECTION AGAINST SHOCK HAZARD CONNECT TO PROPERLY GROUNDED OUTLETS ONLY. *CERTAIN INTERNAL PARTS ARE INTENTIONALLY NOT GROUNDED AND MAY PRESENT A RISK OF ELECTRIC SHOCK ONLY DURING SERVICING. SERVICE PERSONNEL DO NOT CONTACT THE FOLLOWING PARTS WHILE THE APPLIANCE IS ENERGIZED. IF PROVIDED FAN MOTOR, L.V TRANSFORMER OR TIMER. *RISK OF ELECTRIC SHOCK, NON REMOVABLE FASTENERS ARE PROVIDED BECAUSE OF INTERNAL HIGH VOLTAGES. DO NOT REMOVE FASTENERS.</p>
<p>*NOT FOR BUILT-IN INSTALLATION</p>	