



Nemko Korea Co., Ltd.  
 67-1 & 300-2, Osan-ri, Mohyeon-myeon, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea 449-852  
 Tel. 82 31 330 1700 Fax. 82 31 322 2332



**November 17, 2011**

NEMKO CANADA, INC.  
 303 River Road, Ottawa Ontario  
 K1V1H2, CANADA

www.nemko.com

**Subject : Revision of test report certified under FCC ID : C5F7NF9FMO180N**

Dear TCB,

We, Nemko Korea, found an error in the test report (No. : NK-11-E-570) that certified under FCC ID : C5F7NF9FMO180N. It has happened by typo error on the test report.

Hereby we re-issue the corrigendum test report according to customer's request. Please be noticed this.

We are kindly ask TCB to accept this revised test report without further action.

We made corrections on page 5 in test report (No. NK-11-E-570) as follows :

	Before	After
Magnetron Type	RM248 (TOSHIBA)	2M248 (TOSHIBA)

A revised test report was attached with the e-mail.

Thank you again for your support and service to the Nemko Korea.

Sincerely,

Hyunho Kim  
 EMC Manager & Chief Engineer

