



July 25, 2001

Underwriters Laboratories Inc.
333 Pfingston Road
Northbrook, Illinois 60062-2096
U.S.A.

**Subject: Statement of Modification
FCC ID: C5F7NFCML510B**

Gentlemen:

The model **L510B1** is exactly the same construction as model **L510B (FCC ID : C5F7NFCML510B)** except for the followings.

No.	Item	L510B		L510B1		Remark
		Loc.	Part-Desc.	Loc.	Part-Desc.	
1	Model Name	L510B		L510B1		Same FCC ID
2	Panel		L150X1M-2		L150X2M-1	
3	Array Component	RP11,RP12, P13	300 Ohm, Bead			Eliminated Parts
4	Array Component	RP1~RP10	300 Ohm, Bead	RP1~RP10	33 Ohm, Resistor	Changed Spec.
5	DC/AC Inverter		BAI-1503		FLI-1501, HK1512DW	Changed Spec.
6	Main PCB		Size: 154 x 100		Size: 138 x 100	Changed a PCB Pattern

Should you have any questions or comments concerning the above, please contact the undersigned.

Joon H. Lee
Chief of EMC Group
IST Co.,Ltd.