


INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

Radiated Emission – Base Unit



Front View



Rear View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

Radiated Emission – Base Unit



Front View



Rear View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

Radiated Emission – Handset



Front View



Rear View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs – Mode: Talk

Conducted Emission – Model: 60CN57-2



Front View



Right Side View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs – Mode: Talk

Conducted Emission – Model: 60CN57-2




Left Side View


INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs – Mode: Talk

Conducted Emission – Model: CY-936-2



Front View



Right Side View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs – Mode: Talk

Conducted Emission – Model: CY-936-2



Left Side View


INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs – Mode: Ringing with Charging with 60CN57-2 Base Unit

Conducted Emission



Front View




Right Side View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs – Mode: Ringing with Charging with 60CN57-2 Base Unit

Conducted Emission



Left Side View