

Cybiotronics Far East Ltd.

Attn.: Hermosa


Fm: Angel lam

CY-936/936AM/932(XXX)

March 26, 09 (4)

Re: label locations for goods selling to BOTH USA & Canada

(A) Label location on main base




a) CY-936 Base Unit

- 1) FCC Part 15, ETL (C&US)
By engrave
- 2) FCC HAC label (UL label material)

CY-936 - 2 **HAC**
COMPLIES WITH 47 CFR PART 68
REQUIREMENTS
REGISTRATION NO. US:CACW400B936001
IC REN: 0.0
REQUIRED JACKS (USOC): RJ11C
FCC ID: CAC936001
IC: 2340A-936B
CYBIOLINK


17mm

38mm



D) CY-936AM Base Unit

CY-936AM



8. FCC Part 15, ETL (C&US)
By engrave (Content same as 1))

9) FCC HAC lable (UL label material)

60CN57-2 **HAC**
COMPLIES WITH 47 CFR PART 68
REQUIREMENTS
REGISTRATION NO. US:CACW400B936001
IC REN: 0.0
REQUIRED JACKS (USOC): RJ11C
FCC ID: CAC936001
IC: 2340A-936B

CITIZEN

17mm

38mm

(C) Label location in handset

5. Label on the handset bottom

Disconnect all telephone line from the wall-outlet before replacing battery. Débrancher les lignes téléphoniques avant le remplacement des piles. Desconectar las líneas telefónicas antes de sustituir las pilas.

Size: 32mm x 10mm

6. IC label: %ZLA0936I000


IC: 2340A-936B

14mm x 5mm

7. FCC ID label


FCC ID: CAC936001

Size: 14mm x 5mm



FCC ID label

Handset 底部



c) Handset

5. label on handset bottom

Disconnect all telephone line from the wall-outlet before replacing battery. Débrancher les lignes téléphoniques avant le remplacement des piles. Desconectar las líneas telefónicas antes de sustituir las pilas.

