

Comments /Response for Upload:

- 1) There appears to be a increase in field strength, but this may be due to matching, antenna changes. Please comment on if there is any change to the output drive levels.

Response:

*There has been no change to output drive levels. The extent of changes is that two capacitors used to tune the antenna were changed.*