

To Whom It May Concern:

The 5894PI-1 is identical to the 5894PI, with the exception that minor PCB changes were made to accommodate changes in the motion sensor, while these changes did not affect the layout of the rf circuitry, an antenna tuning cap did have to be changed. Please also note the label and label position are shown in the ' LABEL.pdf ' Exhibit. Since the label is molded into the plastic, and white on did not photograph well, it was decided to show you the drawing.

Yours Sincerely,
Greg Barbato