

From: [Iris](#)

To: [Mike Kuo](#) ; [ss](#)

Sent: Wednesday, August 15, 2007 6:38 PM

Subject: Re: RHINE ELECTRONIC CO., LTD., FCC ID: CHQRH787T, Assessment NO.: AN07T7092, Notice#1

Dear Mike,

Ans#1: Please refer to the updated schematic as attachment.

If you have any question, please let us know ASAP.

IRIS

----- Original Message -----

From: [Mike Kuo](#)

To: [ss](#) ; [Iris](#)

Sent: Wednesday, August 08, 2007 12:58 PM

Subject: RHINE ELECTRONIC CO., LTD., FCC ID: CHQRH787T, Assessment NO.: AN07T7092, Notice#1

Hi S.S.:

Q#1: According to the block diagram, a 303.875MHz oscillator is used but in the schematic diagram, there are only a 10MHz oscillator found. Again, please check and update all required files to match the radio capability.

Best Regards,

Mike Kuo

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

No virus found in this incoming message.

Checked by AVG Free Edition.

Version: 7.5.476 / Virus Database: 269.11.8/940 - Release Date: 8/6/2007 4:53 PM