



Tim Dwyer <rfspectrum@gmail.com>

---

## revised: Toshiba Corporation, FCC ID: CJ6UPLL3APC, Assessment NO.: AN09T9932, Notice#2

1 message

---

Claire Hoque <claire.hoque@ccsemc.com>  
To: "Timothy M. Dwyer" <tim.dwyer@ccsemc.com>

Fri, Dec 11, 2009 at 3:16 PM

Claire Hoque  
Compliance Certification Services  
47173 Benicia Street  
Fremont, CA 94538, USA  
Tel: (510) 771-1123  
Fax: (510) 661-0888

-----Original Message-----

From: Timothy M. Dwyer  
Sent: Friday, December 11, 2009 12:06 PM  
To: Thu Chan; Claire Hoque  
Cc: Timothy M. Dwyer  
Subject: Toshiba Corporation, FCC ID: CJ6UPLL3APC, Assessment NO.:  
AN09T9932, Notice#2

Hello Thu, Claire,

Review of the application is complete. This is notice 2. Response to notice 1 were acceptable.

Q4. Probe calibration certificates and system check plots referenced on page 29 of the SAR report were not included with application files. Worst case SAR plots were included in the test report, but complete SAR plots were not in the application documents. Please upload or send these documents so that this application can be send to the certifier.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

Best regards,

Tim Dwyer  
Technical Reviewer

---

### 5 attachments

 **5\_Certificate of System Validation Dipole - D1900V2 SN 5d043.pdf**  
583K

 **1\_System Check Plots.pdf**  
285K

 **2\_SAR Test Plots.pdf**  
581K

 **3\_Certificate of E-Field Probe - EX3DV4 SN3686.pdf**  
678K

 **4\_Certificate of System Validation Dipole - D835V2 SN 4d002.pdf**  
635K

---