



Washington Laboratories, Ltd.

7560 Lindbergh Drive Gaithersburg, Maryland 20879 (301) 216-1500 Fax (301) 216-1590
website: <http://www.wll.com> email: info@wll.com

June 6, 2008

AmericanTCB
6731 Whittier Avenue, Suite C110
McLean, VA 22101

RE: Emissions Designator Corrections: Class II Permissive Change Request

FCC ID: CN2EPAH-A90

Dear Sirs,

The above-reference FCC ID was submitted to AmericanTCB in November of 2003. In the calculation of the emissions designator, an incorrect maximum modulation frequency was used

The correct modulation frequency is 2000 Hz. The emission designator should be 10K4F1D.

Please review the attached revised report and advise if you have any questions.

Thank you for your attention and kind regards,

Sincerely,

A handwritten signature in blue ink, appearing to read "Michael Violette".

Michael Violette, PE

President