
SETUP PHOTOS 11.


ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP



FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL CCS.


RADIATED RF MEASUREMENT SETUP






TEL: (510) 771-1000

RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION











TEL: (510) 771-1000 FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL CCS.





END OF REPORT

Page 112 of 112