



Physio-Control, Inc.

11811 Willows Road NE, P.O. Box 97006, Redmond, WA 98052

Tel 425.867.4000 Toll-free 800.442.1142

www.physio-control.com

February 6, 2013

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Re: Request to Change in Identification:

Dear Examiner,

This change of identification request applies for FCC ID: CZO-CMMPHYSIO21 as established in 47CFR 2.933(b) for a currently approved device. This application by Physio-Control, Inc will establish a new FCC ID: CZO-CMMPHYSIO21 under Physio-Control, Inc Grantee code for purpose of marketing. The original grant to Redpine Signals Inc will remain in effect per 2.933(b).

1. The original identification is FCC ID:XF6-RS9110N1103
2. The original grant date is 09/20/2012
3. The equipment is electrically identical, only application and FCC ID are different
4. The original test results are applicable and representative of this changed device
5. Exterior photographs are include in this application

The following files are electronically submitted as attachments:

Authorization letter from original grantee
External Photos of New Application
FCC ID Label Format and location of New Application

Sincerely,

A handwritten signature in black ink, appearing to read "Matt Hedlund", is written over a faint, larger signature.

Matt Hedlund
Compliance Engineering
Physio-Control, Inc.
11811 Willows Road
Redmond, WA 98052