

July 26, 2023

Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

Re: Applicant: Physio-Control, Inc.  
FCC ID: CZO23L4N1  
Part 2.933(b) Change in Identification of Equipment

Physio-Control, Inc. requests a change in identification of a currently certified device under Part 2.933(b).

The original equipment identification is FCC ID: RI7LE910CXNF.

The original Grantee: Telit Communications S.p.A was granted approval on October 22, 2018.

The original test data filed by Telit Communications S.p.A continues to be representative of the newly identified device. There are no changes to the hardware or software.

This change in identification is requested for the newly identified device, FCC ID: CZO23L4N1, which is physically and electrically identical as defined by Part 2.907, to the originally approved module.

Photographs as required under Part 2.933(5) and FCC ID label are submitted with this request.

Please let us know if you might require anything further to assist with your review of this Change in Identification of Equipment.

Thank you,



Timothy Rand  
Sr Compliance Standards Engineer  
Stryker Emergency Care  
11811 Willows Rd NE  
Redmond WA 98052  
+1 425 867 4477  
tim.rand@stryker.com  
www.physio-control.com