
# Appendix C. Setup Photographs

#### **Conducted Emission**

Mode 1~2



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : C1 of C7
Report Issued Date : Feb. 19, 2008
Report Version : Rev. 01

Report No.: FR812117-C





SIDE VIEW

### Mode 3




FRONT VIEW


SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : C2 of C7
Report Issued Date : Feb. 19, 2008
Report Version : Rev. 01





**REAR VIEW** 



SIDE VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : C3 of C7
Report Issued Date : Feb. 19, 2008
Report Version : Rev. 01





#### Mode 4

FRONT VIEW





**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : C4 of C7
Report Issued Date : Feb. 19, 2008
Report Version : Rev. 01



SIDE VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : C5 of C7
Report Issued Date : Feb. 19, 2008
Report Version : Rev. 01






## **Radiation Emission**

Mode 1-6



FRONT VIEW



REAR VIEW

SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : C6 of C7
Report Issued Date : Feb. 19, 2008
Report Version : Rev. 01






Mode 7

FRONT VIEW





**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page Number : C7 of C7
Report Issued Date : Feb. 19, 2008
Report Version : Rev. 01