

From: ssliou [ssliou@etc.org.tw]
Sent: Wednesday, November 02, 2005 1:35 AM
To: Michael Heckrotte
Cc: R00/???; R00/???
Subject: Re: Tecom Co., Ltd., FCC ID: D6XWL5011S, Assessment NO.: AN05T4897, Notice#4

Dear Michael,

#14 and 15, The channel outside the authorized frequency range is blocked by factory setting. The use of unauthorized frequency is prevented under normal usage. Please refer to attached OEM Guide.

#16 The misleading statement is deleted. Please refer to attached OEM Guide.

Best regards,

S. S. Liou
Engineer / EMC Dept. II
Electronics Testing Center, Taiwan

----- Original Message -----

From: "Michael Heckrotte" <michael.heckrotte@ccsemc.com>
To: "SS Liou (E-mail)" <ssliou@etc.org.tw>
Cc: "Iris (E-mail)" <iris@etc.org.tw>
Sent: Thursday, October 27, 2005 9:29 AM
Subject: FW: Tecom Co., Ltd., FCC ID: D6XWL5011S, Assessment NO.: AN05T4897, Notice#4

Dear SS,

14. The installation manual appears to document the software that will be furnished to the end user by the OEM integrator. Page 4 of the installation manual indicates that Infrastructure Mode or Ad Hoc Mode can be selected. When the Infrastructure mode is selected please explain how the device will be restricted to prevent operation on a channel that is outside the frequency range that is intended to be authorized by the FCC grant.

15. Pages 4 and 5 of the installation manual indicate that Country and Channel can be selected in the Ad Hoc Mode. When the Ad Hoc Mode is selected please explain how the device will be restricted to prevent the end user from selecting a channel that is outside the frequency range that is intended to be authorized by the FCC grant.

16. The FCC statements on page 14 of the installation manual indicate that the device must be installed by a professional technician/installer. The OEM integrator is not a professional installer, the filing does not support or require professional installation, therefore this statement is not appropriate. Please remove it from the installation manual.

Best Regards,
Mike

-----Original Message-----

From: Compliance Certification Services
[mailto:michael.heckrotte@ccsemc.com]
Sent: Wednesday, October 26, 2005 6:02 PM
To: Michael Heckrotte
Subject: Tecom Co., Ltd., FCC ID: D6XWL5011S, Assessment NO.: AN05T4897,
Notice#4

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.