



# **ROGERS LABS, INC.**

4405 West 259<sup>th</sup> Terrace  
Louisburg, KS 66053  
Phone / Fax (913) 837-3214

July 3, 2012

Timco Engineering Inc.  
849 NW State Road 45  
Newberry, FL 32669

Applicant: Lectrosonics, Inc.  
581 Laser Road  
Rio Rancho, NM 87124

Re: Label Sample revision for FCC ID: DBZWME

Gentlemen

Please accept this revised label sample for use in replacing the original exhibit submitted with application. It was brought to our attention the label did not comply with CFR47 2.1925 identification of equipment requirements. The label has been corrected by placing the letters "ID" in the FCC ID test line. No product has been distributed and all produced products have been correctly labeled using the corrected labeling. Please process this information to the FCC for replacement of incorrect label sample exhibit originally submitted.

Should you require any further information, please contact the undersigned.

Thank you for your consideration in this matter.

Sincerely,

Scot Rogers  
Rogers Labs, Inc.  
Enclosures