


Test Site	WZ-SR5	Test Engineer	Lynn Yang
Test Date	2024-10-09	Test Mode	Mode 3

Port A

Channel 606.000MHz



Channel 607.875 MHz




Channel 614.125 MHz




Port A


Channel 615.875MHz



Channel 657.000MHz




Channel 662.875MHz




Port B


Channel 606.000MHz



Channel 607.875 MHz




Channel 614.125 MHz




Port B


Channel 615.875MHz



Channel 657.000MHz




Channel 662.875MHz




Port C


Channel 606.000MHz



Channel 607.875 MHz




Channel 614.125 MHz




Port C


Channel 615.875MHz



Channel 657.000MHz




Channel 662.875MHz




Port D


Channel 606.000MHz



Channel 607.875 MHz




Channel 614.125 MHz




Port D


Channel 615.875MHz



Channel 657.000MHz



Channel 662.875MHz



Test Site	WZ-SR5	Test Engineer	Lynn Yang
Test Date	2024-10-09	Test Mode	Mode 7

Port A

Channel 606.275MHz



Channel 607.600 MHz




Channel 657.000 MHz



Port A


Channel 662.600MHz




Test Site	WZ-SR5	Test Engineer	Lynn Yang
Test Date	2024-10-01 2024-10-09	Test Mode	Mode 8

Port A


Channel 606.275MHz



Channel 607.600 MHz




Channel 657.000 MHz




Port A

Channel 662.600MHz




Port B


Channel 606.275MHz




Channel 607.600 MHz



Channel 657.000 MHz





Channel 662.600MHz




Port C


Channel 606.275MHz




Channel 607.600 MHz



Channel 657.000 MHz




Channel 662.600MHz




Port D


Channel 606.275MHz



Channel 607.600 MHz



Channel 657.000 MHz



Channel 662.600MHz

