
Appendix C. Set up Photograph

Conducted Emission

Mode 1 and 2



FRONT VIEW


REAR VIEW


SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C5
Report Issued Date : Dec. 15, 2006

Report No.: FR6N2811

Report Version : Rev. 01





SIDE VIEW

Mode 3



FRONT VIEW


SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C5

Report Issued Date : Dec. 15, 2006

Report Version : Rev. 01





REAR VIEW

SIDE VIEW

SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C5

6N2811

Report Issued Date : Dec. 15, 2006 Report Version : Rev. 01

Radiation Emission

Mode 1~6



FRONT VIEW

REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C4 of C5
Report Issued Date : Dec. 15, 2006

Report No.: FR6N2811


Report Version : Rev. 01



Mode 7~9

FRONT VIEW

REAR VIEW



SPORTON International Inc.

 TEL: 886-2-2696-2468
 Report Issued Date : Dec. 15, 2006

 FAX: 886-2-2696-2255
 Report Version : Rev. 01