



# Intertek Testing Services

## ETL SEMKO

Report No.: 0214353

Tested By: Ben, Report No.: 0214353


Scan Settings (1 Range)

Frequencies			Receiver Settings					
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP

Meas Time: 1 s  
Subranges: 16  
Acc Margin: 20dB

Transducer No. Start Stop Name  
21 9k 30M EW0698



Ctrl No.: *NA*



# Intertek Testing Services

## ETL SEMKO

Report No.: 0214353

Tested By: Ben, Report No.: 0214353

### Scan Settings (1 Range)

Frequencies			Receiver Settings						
Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge	
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB	

### Final Measurement Results:

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV
4.03000	28.3	48.0

\* limit exceeded

Ctrl No.: M/R