

EchoStar Technologies L.L.C. 90 Inverness Circle East Englewood, CO 80112 (303) 706-5234

February 4, 2014

Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

RE: DKNCR90

To Whom It May Concern:

The ID:072 client software and associated drivers:

- will not initiate any transmission on DFS frequencies without initiation by a master device
- will not transmit beacons on DFS frequencies/channels
- do not support ad-hoc or peer to peer networks

Sincerely,

Ian Schroeder

Regulatory Compliance Engineer

A Selvel-

EchoStar Technologies L.L.C.