



Intertek Testing Services

ETL SEMKO

Charging Mode

Report No.: 0215841

Tested By: Hong, Report No.: 0215841

Scan Settings (1 Range)

----- Frequencies -----||----- Receiver Settings -----|


Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	9k	30M	EW0698

dBuV



PAGE 1

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Charging Mode

Report No.: 0215841

Tested By: Hong, Report No.: 0215841

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement

no Results

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

RX Mode

Report No.: 0215841

Tested By: Hong, Report No.: 0215841

Scan Settings (1 Range)

----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement: x QP

Meas Time: 1 s


Subranges: 16

Acc Margin: 20dB

Transducer No. Start Stop Name

21 9k 30M EW0698

dBuV



PAGE 1

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

RX Mode

Report No.: 0215841

Tested By: Hong, Report No.: 0215841

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN OFF	60dB

Final Measurement

no Results

Ctrl No.: N/A