

Subject: Re: ^<H;G DT9T-9800
Date: Mon, 02 Dec 2002 18:01:14 -0800
From: Dennis Ward <dennis@yosemite.net>
Reply-To: dward@atcb.com
To: Vivi@adt.com.tw, alan_lane@adt.com.tw
References:
1 , 2

Hi Vivi

finally on the DTR - the report lists an average reading for 433MHz fundamental. Please note that this is no accurate. Security/remote control items under 15.231 must use Pulse Width Modulation duty cycle averaging, not video averaging. The device is still compliant in peak reading mode, but the report is in error using average not Pulse width modulation duty cycle averaging. Please correct your reports to reflect the proper techniques

Thanks

Dennis