

Per 15.203, the antenna is internal and permanently attached. It is not intended to be serviced by the customer and is, therefore only serviceable by Logitech, Inc. authorized personnel.

The antenna is a chip antenna, Johanson part# 190482-0000 with 2.99dBi max peak gain.

