

Responses to Non-Conformities (Ref # E00-000505-1) FCC ID: E36LRP800

Item 1. Please show Compliance to FCC15.21

5Jan01: New Manuals have been uploaded which contain the proper statement to comply with 15.21

Item 2. Please indicate which documents are to be kept confidential as per section 0.459.

5Jan01: This has been clarified to show compliance with section 0.459

Item 3. All schematics reference model LRP820, please provide schematics for model LRP830.

5Jan01: New schematics have been uploaded, and a description of the difference.

Item 4. There is no indication that radiated emissions were performed below 30MHz, Please show compliance to FCC 15.33

5Jan01: New report indicates proper frequency range tested

Item 5. No indication of proper resolutions used for radiated measurements below 30MHz

5Jan01: New report shows proper resolutions below 30MHz

Item 6. Please show compliance to the requirements in 15.203

5Jan01: TNC connector is used to comply with 15.203

Item 7. Please show compliance to 15.205 below 30MHz

5Jan01: New report shows compliance to 15.205 below 30MHz

Item 8. Please show compliance to 15.209 below 30MHz

5Jan01: New report shows compliance to 15.209 below 30MHz

Item 9. Temperature Stability data in report, page 63, has NO indication of voltage used during test. Please provide voltages used.

5Jan01: New report provides the voltages used for the temperature test.

Item 10. Please show compliance to 15.225(a) for all three antennas.

5Jan01: New report shows compliance to 15.225(a) for all three antennas