



GLOBAL PRINTING ... ENABLED.

ISO 9001 Registered Worldwide

14600 Myford Road, P.O. Box 19559
Irvine, California 92623-9559
Telephone (714) 368-2737
Fax (714) 368-2941
www.printronix.com

5/20/2004

CKC Laboratories
5473-A Clouds Rest
Mariposa, CA 95338
Phone: (209) 966-5240
Fax: (209) 742-6133

Attention: Report Department

Subject: Letter of Differences

To Whom It May Concern:


This letter is to inform you of the differences between the old system listed under FCC ID E5A-ADRFID and the new system with the requested FCC ID E5A-AD2RFID. The first difference is the transmitter has been moved from the media portion of the printer to the electronics portion of the printer. This change has not affected any of the electrical properties of the printer, nor has it changed the schematics, operational description, functionality or any other portion of the printer and transmitter.

The second difference is a new antenna. The old antenna has been replaced. This change has forced a change to the operational description document, but has not affected any other portion of the printer, transmitter or documentation.

In short, there are three changes. These are transmitter has been relocated, new antenna and updated operational description. If there should be any questions or concerns, please feel free to contact Mr. Schumaker or myself.

Best Regards,


Josh Wiseman
EMC/Product Safety Eng.
Tel: (714) 368-2737
Fax: (714) 368-2941


Dick Schumaker
Director Product Engineering
Tel: (714) 368-2802
Fax: (714) 368-2941