

www.elliottlabs.com Sunnyvale, CA 94085-3518 408-245-3499 Fax

American TCB

October 12, 2007

RE: FCC ID:E5MDS-9810 IC: 3738A-MDS9810 Attention: Douglas E. Noble

Please find our responses to your comments on this application below:

1. The Industry Canada Company number and Unique Product Number is missing from the label drawing. Please revise label drawing to include this information.

I have uploaded a new label document

2. Confidentiality letter for IC and FCC does not include Operational Description. Please revise both FCC and IC confidentiality letters.

Both letters request the "Theory of Operation" be held confidential.

You are correct Subject line left out Theory of Operation.

3. Company Number and Unique Product Number are incorrect on the first page of the test report. Please correct.

This has been corrected. A revised report has been uploaded.

Regards,

David Levelotte

David Guidotti Senior Documentation Specialist