



GE MDS

175 Science Parkway, Rochester, New York 14620 USA  
(585) 242-9600 Phone  
(585) 242-9620 Fax  
December 19<sup>th</sup>, 2017

**FEDERAL COMMUNICATIONS COMMISSION**  
7435 Oakland Mills Road  
Columbia, MD 21046  
U.S.A.

**Subject: Tune Up procedure for the LW700**


**Applicant: GE MDS LLC.**  
**Product: MDS LW700**  
**FCC ID: E5MDS-LW700**

Dear Sir/Madam,

The LW700 has no customer or user tune up procedure. This is a DSP/microprocessor controlled based unit. All RF power settings, modem settings, are saved into non-volatile memory. The unit is factory calibrated and there are no user calibration settings available. There are no tune up procedures available to the end user. All tune ups must be done by the GE MDS factory.

If you have any queries, please do not hesitate to contact me at 585 242-8440:

Yours truly,

Signed:  Name: Dennis McCarthy .....

**Dennis McCarthy**  
Agency Compliance Engineer  
GE MDS  
175 Science Parkway  
Rochester NY 14620  
**Phone (585) 242-8440**  
Email Dennis.McCarthy2@GE.com