



GE MDS

175 Science Parkway, Rochester, New York 14620 USA
(585) 242-9600 Phone
(585) 242-9620 Fax
June 27th, 2008

FEDERAL COMMUNICATIONS COMMISSION
7435 Oakland Mills Road
Columbia, MD 21046
U.S.A.

Subject: Tune Up procedure for the Mercury3600

Applicant: GE MDS LLC.
Product: MDS MERCURY3600
FCC ID: E5MDS-MERCURY3600


Dear Sir/Madam,
Elliott TCB
684 West Maude Ave.
Sunnyvale, CA. 94085

The MERCURY3600 is a FCC part 90.1301 subpart Z, site coordinated transceiver. This is a DSP/microprocessor controlled based unit. All RF power settings, modem settings, are saved into non-volatile ram. The unit is factory calibrated and there are no user calibration settings available.

There are no tune up procedures available to the end user. All tune ups must be done by the GE MDS factory.

If you have any queries, please do not hesitate to contact me at 585 242-8440:

Yours truly,

Signed:  Name: Dennis McCarthy

Dennis McCarthy
Agency Compliance Engineer
GE MDS
175 Science Parkway
Rochester NY 14620
Phone (585) 242-8440
Email Dennis.McCarthy2@GE.com