

August 22, 2005



RE: Microwave Data Systems
FCC ID: E5MDS9790


1) Please confirm that radiated spurious emissions were done using a substitution method. This cannot fully be determined given the results shown.

Response: Table has been included. Revised report uploaded.

2) Test report does not show tabular data for output power, although it is mentioned in one of the tables. Please update.

Response: Data has been revised to include detail substitution levels. Revised report uploaded.

Regards,



Juan Martinez
Senior EMC Engineer
JM/dmg