

RE: BEHAVIOR TECH COMPUTER CORP

FCC ID: E5XKB5107A

Dear Tim,

Here are our answers,

1) It is uncertain if the FCC ID on the label is correct or not because of the low-resolution on the label provided. Please review and provide a higher resolution label.

ANS: I have uploaded a clear label, refer to file "label & location update.pdf"

2) Cable positioning for the keyboard does not appear to necessarily following ANSI C63.4 – 2003, 6.2.1.2. See NOTE contained in this section. Please review, comment, and/or correct as necessary.

ANS: Normally, my engineer will rout the keyboard's cable on the other side of PC, but in this case, the data is worse than it was put on the same side with mouse's cable.

Please review the supplementment.

Thanks

Daphne Liu