



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

October 11, 2002

RE: Behavior Tech Computer Corporation

FCC ID: E5XMSM951

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Please provide the updated photographs specified in your last email.
- 2) The internal photographs appear to be missing a few photographs. The top and bottom of all boards has not clearly been shown.

Timothy R. Johnson
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.