

LABEL ATTESTATION

6/30/2017

Gentlemen:

This letter is to attest that there is not space available on the smoke detector due to other NFPA required labeling that cannot be alternatively placed in the manual and therefore don't have enough room to include the CFR Title 47 §15.19(3) 2 condition statement. Alternatively, we have contained the 2 condition statement in the Users Instructions in order to satisfy the specified requirements in CFR Title 47 §15.19(3)

If you have any questions feel free to contact me +1 (760) 438-7179

Sincerely,

Josh Hansen
Engineering Manager, Regulatory