






NOTES: (UNLESS OTHERWISE SPECIFIED)

- 1 MARK ASSEMBLY DASH NUMBER AND REVISION LETTER USING 12 (3.0) HIGH CHARACTERS, PERMANENT INK, CONTRASTING COLOR, APPROXIMATELY WHERE SHOWN.
- 2 APPLY GLYPH (ITEM 36) TO TUNING SCREW AFTER TUNING.
- 3 APPLY RTV (ITEM 35) ON PCB BELOW BATTERY (B1) THEN PRESS BATTERY FLUSH TO PCB. SMALL AMOUNT OF RTV SHOULD BE SEEN ON SIDE OF BATTERY FOR INSPECTION.
- 4 SOLDER BATTERY TABS AS SHOWN IN DETAIL C AND TRIM TABS TO .05 - .07 LONG.
- 5 PLACE .50 X .25 PIECE OF TAPE (ITEM 37), BETWEEN BATTERY AND BATTERY TAB AS SHOWN IN DETAIL B.
- 6 BATTERY TABS MUST NOT BE BENT AS SHOWN IN DETAIL B.
- 7 BOTTOM VIEW OF SWITCH IS SHOWN IN DETAIL A. NOTE ORIENTATION OF THE PINS (1 - 2) ALONG WITH SMALL TABS TO INSTALL SWITCHES CORRECTLY.



BOARD OUTLINE

SEE SEPARATE PARTS LIST

Linear
CARLSBAD, CA

[illegible]

DO NOT SCALE DRAWING