



19-NOV-2004

Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, Maryland 21046

RE: Tune-up Procedure for FCC ID: EHASMC46 GSM Module in 700C Hand Held Computer

To whom it may concern,

The MC46 tri-band GSM module requires no adjustments of components after assembly. The 700C hand held computer host device, likewise, requires no adjustments of components after assembly. Settings for radio and hand held computer operation require specialized equipment only available to Intermec manufacturing and service personnel.

Please Contact me if there are any questions.

Yours truly,

Scott J. Holub

Regulatory Compliance Engineer III Intermec Technologies Corporation

550 Second Street S.E.

Cedar Rapids, IA 52401 USA

Intermec Technologies Corporation

6001 36th Avenue West Everett, Washington 98203 United States tel 425.348.2600 fax 425.355.9551

www.intermec.com